


WPU Wiring Diagram

PE					PE					PE					PE					PE				
PE					PE					PE					PE					PE				
L					L					L					L					L				
400					400					400					400					400				
400					400					400					400					400				
74					74					74					74					74				
5					5					5					5					5				
5					5					5					5					5				
5					5					5					5					5				
12					12					12					12					12				
12					12					12					12					12				
1					1					1					1					1				
2					2					2					2					2				
3					3					3					3					3				
4					4					4					4					4				
5					5					5					5					5				
6					6					6					6					6				
7					7					7					7					7				
8					8					8					8					8				
9					9					9					9					9				
10					10					10					10					10				
11					11					11					11					11				
12					12					12					12					12				
13					13					13					13					13				



Models

3R1C1DR410.230/1/60.DC
9E1C2DR410.230/1/60.DC

S.N	Label	Description
1	PF2	Evaporator fan overload
2	PV	Brown-out circuit used for compressor protection
3	KA3	Compressor pilot relay
4	KA4	Heater pilot relay
5	HP1	Condenser fan switch
6	EH1-3	Electric heaters
7	EH	Crankcase heater
8	FU	Thermal fuse for heating
9	TW	Temperature switch for heating
10	PF1	Air pressure differential switch
11	C	Start capacitor for compressor
12	C1	Capacitor for condenser fan
13	LP	Low-pressure switch
14	HP	High pressure switch
15	KM2	Electric heaters AC contactor
16	KM1	Compressor AC contactor
17	MC	Compressor
18	MF2	Evaporator fan/Supply fan
19	MF1	Condenser fan
20	FT	Compressor overload
21	TK1	Condenser fan overload
22	YE	Air damper actuator
23	QF1&QF2	Breaker